


Rudersberg, Zumhof

Fotodokumentation Bohrung EKB 1




Fotodokumentation Bohrung EKB 1



Tiefe (m)
1 2 - 1 3
1 3 - 1 4
1 4 - 1 5
1 5 - 1 6
1 6 - 1 7
1 7 - 2 0 (KV)
2 0 - 2 2 (KV)
2 2 - 2 3
2 3 - 2 4
2 4 - 2 5
2 5 - 2 6
2 6 - 2 7

Fotodokumentation Bohrung EKB 1



Tiefe (m)

27 - 28

28 - 29

29 - 30

30 - 31

31 - 32

32 - 33

33 - 34

34 - 35

35 - 36

36 - 37

37 - 38

38 - 39

Fotodokumentation Bohrung EKB 1



Tiefe (m)

39 - 40

40 - 41

41 - 42

42 - 43

43 - 44

44 - 45

45 - 46

46 - 47

47 - 48

48 - 49

49 - 50

Fotodokumentation Bohrung EKB 1



Tiefe (m)

50 - 51

51 - 52

52 - 53

53 - 54

54 - 55

55 - 56

56 - 57


57 - 58

58 - 59

59 - 60

60 - 61

Fotodokumentation Bohrung EKB 1



Fotodokumentation Bohrung EKB 1



Tiefe (m)

75 - 76

76 - 77

77 - 78

78 - 79

79 - 80

80 - 81

81 - 82

82 - 83

83 - 84

84 - 85

85 - 86

86 - 87

87 - 88

Fotodokumentation Bohrung EKB 1

Tiefe (m)

Bohrkernfoto wird noch eingefügt !



88 - 89

89 - 90

90 - 91

91 - 92

92 - 93

93 - 94